



10066054

CORC

Practitioner's Docket No. 2024729-7014542001

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent Number: 6,790,206  
Issued: September 14, 2004  
Name of Patentee: Dorin Panescu

Title of Invention: COMPENSATION FOR POWER VARIATION ALONG PATIENT CABLES

Mail Stop Issue Fee  
Commissioner for Patents  
PO Box 1450  
Alexandria, VA 22313-1450

ATTENTION: Decision and Certificate of Correction  
Branch of the Patent Issue Division

Certificate  
NOV 10 2004  
of Correction

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT  
FOR PTO MISTAKE (37 C.F.R. section 1.322(a))

1. Attached, in duplicate, is Form PTO--1050, with at least one copy being suitable for printing.


2. The exact page and line number where the error is shown in the patent is:

Page 2 line 11.

3. Please send the Certificate to:

Name: David Burse  
Address: Bingham McCutchen  
Three Embarcadero Center  
San Francisco, CA 94111-4067

Dated: November 4, 2004

  
David Burse  
Attorney of Record

(Request for Certificate of Correction of Patent For PTO Mistake--page 1 of 1)

NOV 12 2004

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,790,206 B2  
DATED : September 14, 2004  
INVENTOR(S) : Dorin Panescu

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On page 2, line 11  
replace "generatorSJ-39249.1,"  
with --generator,--

MAILING ADDRESS OF SENDER:

David Burse  
Bingham McCutchen  
Three Embarcadero Center  
San Francisco, CA 94111-4067

PATENT NO. 6,790,206 B2

No. of additional copies

➡ 1

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

NOV 12 2004

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,790,206 B2

DATED : September 14, 2004

INVENTOR(S) : Dorin Panescu

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On page 2, line 11  
replace "generatorSJ-39249.1,"  
with --generator,--

MAILING ADDRESS OF SENDER:

David Burse  
Bingham McCutchen  
Three Embarcadero Center  
San Francisco, CA 94111-4067

PATENT NO. 6,790,206 B2

No. of additional copies

➡ 1

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

NOV 12 2004